

Menu


HISTORY FILE MAP for year 2009

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



040.07:46-10:16 Complete DSS-14 track lost due to antenna hydrostatic bearing failure. Commanding activity performed later using DSS-54 (U/L only track). 2h30m realtime 512bps as well as 10h00m of 128bps data still in the DSU and played back during this track were lost. DR number pending.